

VEHICLE INSPECTION REPORT

DX70TFN

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 28/10/2020

Year 2020

Mileage 171,650 Km Warranted

Fuel Type Diesel

GVW 7500kg

Colour WHITE

VIN XLRAEL1500L495109

Body Style Box Van

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Roller

Tail Lift Column

ONLY RUNS WITH BOOST PACK, WARNING LIGHTS ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3




OSO4

Features


- Bluetooth connection
- Central locking
- Cruise control
- Cloth seat trim
- Digital radio
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Screen Front
Chipped
UpTo 10mm

8: Door Pad osf
Soiled
Heavy



9: Seat Base Cover of
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK
Seat Condition	Poor

Seat Condition	Poor
----------------	------

Upholstery Condition	Poor
Odour	-

Odour -

Engine Runs	Fault
1	0
2	0
3	0
4	0
5	0
6	0
7	0
8	0
9	0
10	0
11	0
12	0
13	0
14	0
15	0
16	0
17	0
18	0
19	0
20	0
21	0
22	0
23	0
24	0
25	0
26	0
27	0
28	0
29	0
30	0
31	0
32	0
33	0
34	0
35	0
36	0
37	0
38	0
39	0
40	0
41	0
42	0
43	0
44	0
45	0
46	0
47	0
48	0
49	0
50	0
51	0
52	0
53	0
54	0
55	0
56	0
57	0
58	0
59	0
60	0
61	0
62	0
63	0
64	0
65	0
66	0
67	0
68	0
69	0
70	0
71	0
72	0
73	0
74	0
75	0
76	0
77	0
78	0
79	0
80	0
81	0
82	0
83	0
84	0
85	0
86	0
87	0
88	0
89	0
90	0
91	0
92	0
93	0
94	0
95	0
96	0
97	0
98	0
99	0
100	0
101	0
102	0
103	0
104	0
105	0
106	0
107	0
108	0
109	0
110	0
111	0
112	0
113	0
114	0
115	0
116	0
117	0
118	0
119	0
120	0
121	0
122	0
123	0
124	0
125	0
126	0
127	0
128	0
129	0
130	0
131	0
132	0
133	0
134	0
135	0
136	0
137	0
138	0
139	0
140	0
141	0
142	0
143	0
144	0
145	0
146	0
147	0
148	0
149	0
150	0
151	0
152	0
153	0
154	0
155	0
156	0
157	0
158	0
159	0
160	0
161	0
162	0
163	0
164	0
165	0
166	0
167	0
168	0
169	0
170	0
171	0
172	0
173	0
174	0
175	0
176	0
177	0
178	0
179	0
180	0
181	0